

United States Patent and Trademark Office



APPLICATION NO. FILING DATE		ILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.	
09/713,296		11/16/2000	Larry Perrault	² 45197.2	3706	
22828	7590	04/23/2002				
		O BENNETT JO	EXAMI	EXAMINER		
1000 ATCO 10035 - 105	STREET		TRAN A, PHI DIEU N			
EDMONTOR CANADA	N, ALBEI	RTA, AB T5J3T	ART UNIT	PAPER NUMBER		
				3637		
				DATE MAILED: 04/23/2002		

Please find below and/or attached an Office communication concerning this application or proceeding.

• • •		Application No.		Applicant(s)				
•				PERRAULT ET AL.				
	orra Astian Cummont	09/713,296		Art Unit				
	Office Action Summary	Examiner		3637				
	- The MAILING DATE of this communication app	Phi D A	r sheet with the c					
Period for	r Reply							
A SHO THE N - Exten after S - If the - If NO - Failur	ORTENED STATUTORY PERIOD FOR REPLY MAILING DATE OF THIS COMMUNICATION. Issions of time may be available under the provisions of 37 CFR 1.1 SIX (6) MONTHS from the mailing date of this communication. period for reply specified above is less than thirty (30) days, a reply period for reply is specified above, the maximum statutory period or reply within the set or extended period for reply will, by statute eply received by the Office later than three months after the mailing and patent term adjustment. See 37 CFR 1.704(b).	36(a). In no event, how y within the statutory mi will apply and will expire	ever, may a reply be timenimum of thirty (30) days SIX (6) MONTHS from the become ABANDONE	nely filed s will be considered timely. the mailing date of this communication. D (35 U.S.C. § 133).				
1)⊠	Responsive to communication(s) filed on 01 l	November 2000						
2a)□	This action is FINAL . 2b)⊠ Th	nis action is non-	final.					
3)	Since this application is in condition for allow	ance except for f	formal matters, pr	rosecution as to the merits is				
	closed in accordance with the practice under ion of Claims		, 1000 O.D. 11,					
4)⊠	Claim(s) 1-21 is/are pending in the application	n.	ration					
	4a) Of the above claim(s) is/are withdra	awn from conside	eration.					
	Claim(s) is/are allowed.							
	Claim(s) <u>1-17</u> is/are rejected.							
7)⊠	Claim(s) 18-21 is/are objected to.							
	Claim(s) are subject to restriction and/o	or election requi	ement.					
	ion Papers	er						
9)🖂	The specification is objected to by the Examination The drawing(s) filed on is/are: a) ☐ acceptance acceptance are acceptance as a constant acceptance acceptance are acceptance as a constant acceptance acceptance are acceptance acc	ented or b)∏ obie	cted to by the Exa	aminer.				
10)LJ	And light may not request that any objection to t	he drawing(s) be h	ield in abeyance.	See 37 CFR 1.85(a).				
Applicant may not request that any objection to the drawing(s) be held in abeyance. See 37 CFR 1.85(a). 11) The proposed drawing correction filed on is: a) approved b) disapproved by the Examiner.								
'')	If approved, corrected drawings are required in r	eply to this Office	action.					
12)□	The oath or declaration is objected to by the E							
	under 35 U.S.C. §§ 119 and 120							
131	Acknowledgment is made of a claim for foreign	gn priority under	35 U.S.C. § 119((a)-(d) or (f).				
1)							
	1. Certified copies of the priority docume	nts have been re	ceived.					
	2 Certified copies of the priority documents have been received in Application No							
*	3. Copies of the certified copies of the priority documents have been received in this National Stage application from the International Bureau (PCT Rule 17.2(a)). * See the attached detailed Office action for a list of the certified copies not received.							
14)	Acknowledgment is made of a claim for domestic priority under 35 U.S.C. § 119(e) (to a provisional application).							
	 a) The translation of the foreign language p Acknowledgment is made of a claim for dome 	provisional applic	ation has been re	eceived.				
Attachme								
1) No	tice of References Cited (PTO-892) stice of Draftsperson's Patent Drawing Review (PTO-948) formation Disclosure Statement(s) (PTO-1449) Paper No(s	5)	Notice of Inform	ary (PTO-413) Paper No(s) al Patent Application (PTO-152)				

Art Unit: 3637

Specification

1. The disclosure is objected to because of the following informalities: page 8 line 6 "connectors (18) "is confusing. Connectors (18) is not in drawings. Also, lines 2-3 have "hangers (18)", different items need to have different numbers, and the numbers need to be consistent.

Appropriate correction is required.

Claim Rejections - 35 USC § 112

- The following is a quotation of the second paragraph of 35 U.S.C. 112:
 The specification shall conclude with one or more claims particularly pointing out and distinctly claiming the subject matter which the applicant regards as his invention.
- 3. Claims 6, 8, 18, 20 are rejected under 35 U.S.C. 112, second paragraph, as being indefinite for failing to particularly point out and distinctly claim the subject matter which applicant regards as the invention.

Claim 6 line 2 " the bottom of the bottom chord" is lacking antecedent basis

Claim 8 line 3 " the bottom chord" is lacking antecedent basis.

Claim 18 line 3 "partition wall, having a horizontal planar member...." is confusing. It is unclear what is having a horizontal planar member. Does applicant mean to say "the bracket having a horizontal planar member"?

Claim 20 line 2 "comprising a planar member" has the same problem as claim 18 above.

Line 3 "between, and extending beyond, the bottom..." is confusing. Should it be "between, and extending beyond the bottom..."?

Claim Rejections - 35 USC § 102

Art Unit: 3637

4. The following is a quotation of the appropriate paragraphs of 35 U.S.C. 102 that form the basis for the rejections under this section made in this Office action:

A person shall be entitled to a patent unless -

- (b) the invention was patented or described in a printed publication in this or a foreign country or in public use or on sale in this country, more than one year prior to the date of application for patent in the United States.
- (e) the invention was described in a patent granted on an application for patent by another filed in the United States before the invention thereof by the applicant for patent, or on an international application by another who has fulfilled the requirements of paragraphs (1), (2), and (4) of section 371(c) of this title before the invention thereof by the applicant for patent.

The changes made to 35 U.S.C. 102(e) by the American Inventors Protection Act of 1999 (AIPA) do not apply to the examination of this application as the application being examined was not (1) filed on or after November 29, 2000, or (2) voluntarily published under 35 U.S.C. 122(b). Therefore, this application is examined under 35 U.S.C. 102(e) prior to the amendment by the AIPA (pre-AIPA 35 U.S.C. 102(e)).

5. Claims 1-3, 8, 10-11, 13-16 are rejected under 35 U.S.C. 102(e) as being anticipated by Kost (6047503).

Kost (figure 12) shows an improved roof truss having a bottom plate (2A) disposed beneath the roof truss (6), means (24) for attaching the bottom plate to the roof truss (the means 24 inherently is capable of allowing separation of the bottom from the roof truss when the bottom plate is attached to an interior partition wall and the roof truss rises relative to the interior partition wall), the means being a plurality of connectors (24), the connectors being removable (inherently so by removing the fasteners 25A, 25C), the connectors having a plurality of wood fasteners (25A, 25C inherently wood fasteners as they fasten the connectors to the wooden frame) and hangers (24) having a plurality of holes, the wood fasteners connecting the bottom

Art Unit: 3637

plate and the hangers through the holes, the hangers being metallic wrapped around hangers (col 4 last line).

Per claims 10, 11, 13-14, Kost figures (5-7) shows the hangers(7, 8) having perforations (7A) disposed in such a way that if the hanger is severed at the perforation, the hanger and fasteners no longer work to attach the bottom plate to the bottom chord, the hangers (7, 8) being slidably attached to the bottom plate and the bottom chord(the hangers slidable between the plate and the chord before nailing), the hangers being U(8) or H(7) shaped hangers.

6. Claims 1-4 are rejected under 35 U.S.C. 102(b) as being anticipated by Gottlieb (4562683).

Gottlieb (figures 1, 8, 11) shows an improved roof truss having a bottom plate (20) disposed beneath the roof truss, means (10) for attaching the bottom plate to the roof truss (the means inherently is capable of allowing separation of the plate from the truss when the plate is attached to an interior partition wall and the truss rises relative to the wall), the means being removable, frangible connectors (removable by prying the means from the plates).

7. Claims 1-2, 7 are is rejected under 35 U.S.C. 102(b) as being anticipated by Knoth (5561949).

Knoth (figure 1) shows an improved roof truss having a bottom plate (16) disposed beneath the roof truss(42), means(60) for attaching the bottom plate to the roof truss (the means inherently is capable of allowing separation of the plate from the truss when the plate is attached to an interior partition wall and the truss rises relative to the wall), the means being gang plates.

Art Unit: 3637

8. Claims 1, 5 are rejected under 35 U.S.C. 102(b) as being anticipated by Bodtker (5459967).

Bodtker shows an improved roof truss having a bottom plate (29) disposed beneath the roof truss, means(40) for attaching the bottom plate to the roof truss (the means inherently is capable of allowing separation of the plate from the truss when the plate is attached to an interior partition wall and the truss rises relative to the wall), the means being one more connectors slidably attached to the bottom plate and the roof truss (the connector is slidable to attached at different locations of the plate and the truss).

9. Claims 1, 2, 6 are rejected under 35 U.S.C. 102(b) as being anticipated by Eberle (4727700).

Eberle (figure 4) shows an improved roof truss having a bottom plate (28) disposed beneath the roof truss(2), connectors (18) for attaching the bottom plate to the roof truss (the means inherently is capable of allowing separation of the plate from the truss when the plate is attached to an interior partition wall and the truss rises relative to the wall), the connectors being fasteners driven through the bottom plate(28) into the bottom of the bottom chord (2)

10. Claims 1, 2, 8, 9 are rejected under 35 U.S.C. 102(b) as being anticipated by Reinen (4727700).

Reinen (figures 1, 5) shows an improved roof truss having a bottom plate (66) disposed beneath the roof truss (32), connectors (12, the connectors inherently are capable of allowing separation of the plate from the truss when the plate is attached to an interior partition wall and the truss rises relative to the wall) for attaching the plate to the roof truss, the connectors comprising a plurality of wood fasteners (the nail fastening to wood) and hangers having a

Art Unit: 3637

plurality of holes (figure 5, holes at 86) wherein fasteners being driven through the holes in the hangers into the bottom chord, the hangers being frangible (94).

11. Claim 17 is rejected under 35 U.S.C. 102(b) as being anticipated by Symonds (Australia 117042).

Symonds shows an improved roof truss having a bottom chord (4), a bottom plate (5) underneath the bottom chord, means (13, the means inherently is capable of allowing separation of the plate from the truss when the plate is attached to an interior partition wall and the truss rises relative to the wall) for attaching the bottom plate to the bottom chord, spacers (14) disposed between the bottom plate and the bottom chord which create a thermal gap between the bottom plate and the bottom chord.

Claim Rejections - 35 USC § 103

- 12. The following is a quotation of 35 U.S.C. 103(a) which forms the basis for all obviousness rejections set forth in this Office action:
 - (a) A patent may not be obtained though the invention is not identically disclosed or described as set forth in section 102 of this title, if the differences between the subject matter sought to be patented and the prior art are such that the subject matter as a whole would have been obvious at the time the invention was made to a person having ordinary skill in the art to which said subject matter pertains. Patentability shall not be negatived by the manner in which the invention was made.
- 13. Claim 12 is rejected under 35 U.S.C. 103(a) as being unpatentable over Reinen (4669235) in view of Boozer (5743063).

Reinen (figures 1, 5) shows an improved roof truss having a bottom plate (66) disposed beneath the roof truss (32), connectors (12, the connectors inherently are capable of allowing separation of the plate from the truss when the plate is attached to an interior partition wall and the truss rises relative to the wall) for attaching the plate to the roof truss, the connectors

Art Unit: 3637

comprising a plurality of wood fasteners (the nail fastening to wood) and hangers having a plurality of holes (figure 5, holes at 86) wherein fasteners being driven through the holes in the hangers into the bottom chord, the hangers being slidably attached to the bottom plate and the bottom chord (slidable to position to be attached).

Reinen does not disclose the holes being vertically slotted holes.

Boozer discloses slots (figure 8C, 89) for connecting a hanger(89) to other structural members.

It would have been an obvious matter of design choice to modify Reinen to show the holes being vertically slotted holes because applicant has not disclosed that the vertically slots holes solve any stated problem or is for any particular purpose and it appears that the invention would perform equally well with holes.

Allowable Subject Matter

- 14. Claims 18-21 are objected to as being dependent upon a rejected base claim, but would be allowable if rewritten in independent form including all of the limitations of the base claim and any intervening claims.
- 15. The following is a statement of reasons for the indication of allowable subject matter: prior art does not show the improved truss having a bottom chord, a bottom plate beneath the bottom chord, spacers between the bottom plate and the bottom chord forming a thermal gap, means attaching the bottom chord to the bottom plate, a bracket positioned between the bottom plate and the bottom chord, the bracket having a horizontal planar member on top of the bottom plate, the horizontal planar member being attached to vertical planar members on either side of

Art Unit: 3637

extending away from the bottom plate along the top surface of the interior partition wall, the bracket being attached to the top surface of the interior partition wall with fasteners driven through the planar members extending away from the bottom plate; prior art also does not show the improved truss having a bottom chord, a bottom plate beneath the bottom chord, spacers between the bottom plate and the bottom chord forming a thermal gap, means attaching the bottom chord to the bottom plate, a strap located at the intersection of the bottom plate and an interior partition wall, said strap having a planar member positioned between and extending beyond the bottom plate and the bottom chord, fasteners driven through the planar member on either side of the bottom plate to attach the bottom plate to the interior partition wall.

Conclusion

The prior art made of record and not relied upon is considered pertinent to applicant's disclosure. The prior art shows different improved roof trusses.

Any inquiry concerning this communication or earlier communications from the examiner should be directed to Phi D A whose telephone number is 703-306-9136. The examiner can normally be reached on Monday-Thursday.

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Lanna Mai can be reached on 703-308-2486. The fax phone numbers for the organization where this application or proceeding is assigned are 703-872-9326 for regular communications and 703-872-9327 for After Final communications.

Art Unit: 3637

Any inquiry of a general nature or relating to the status of this application or proceeding should be directed to the receptionist whose telephone number is 703-308-1113.

Phi Dieu Tran A April 11, 2002